

# OPERATIONS PERMIT

Name: (owner) WILLIAM R Langley  New Installation  Septic Tank  
Property Location: SR# 1700 + 1703  Repairs  Nitrification Line  
Subdivision \_\_\_\_\_ Lot # \_\_\_\_\_  
TAX ID# \_\_\_\_\_ Quadrant # \_\_\_\_\_  
Contractor: TRACY DENNING Registration # \_\_\_\_\_

Basement with Plumbing:  Garage:   
Water Supply:  Well  Public  Community  
Distance From Well: 50' ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system:  Conventional  Other \_\_\_\_\_  
Size of tank: Septic Tank: Existing gallons Pump Tank: \_\_\_\_\_ gallons  
Subsurface Drainage Field No. of ditches 3 exact length of each ditch 100 ft. width of ditches 3 ft. depth of ditches 18-22 in.  
French Drain: \_\_\_\_\_ Linear feet

PERMIT NO. 15976 Date: 2-3-99  
Inspected by: James E. Mankart  
Environmental Health Specialist

