

HTE # Attempt to Repair

RNETT COUNTY HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH SECTION

18064

OPERATIONS PERMIT

Name: (owner) Luis Campos New Installation Septic Tank Repair

Property Location: SR# 1222 Nitrification Line Expansion
Subdivision _____ Lot # _____ Tax ID # _____ Quadrant # _____

Contractor: Terry Maple Registration # _____

Basement with Plumbing: Garage:

Water Supply: Well Public Community
Distance From Well: _____ ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system: Conventional Other 25% Reduction System

Size of tank: Septic Tank: exist gallons Pump Tank: _____ gallons

Subsurface Drainage Field No. of ditches 2 exact length of each ditch 75 ft. width of ditches 3 ft. depth of ditches 18 in.

French Drain Required: _____ Linear feet

Date: 06-07-06

PERMIT NO. 22968

Inspected by: [Signature]

