

# Certificate of Completio..

No. 3529

Owner Linda Burgess Address \_\_\_\_\_  
(MUST BE FILLED IN) (MAILING ADDRESS)

Contractor Billy Myatt Address \_\_\_\_\_  
(MAILING ADDRESS)

Location of Premises Neills Creek Farms Lot # 51  
(SUBDIVISION, STREET OR ROAD NAME OR NUMBER, LOT NO.)

### Details of Septic Tank System

Kind of Material for Tank:  Concrete  Other \_\_\_\_\_

Size of Tank: Capacity 1000 Gallons

Subsurface Drainage Field: No. of Ditches 4 Exact Length of each Ditch 110 Ft. Width of Ditches 3 Ft. Depth of Ditches 18 Inches

Surface Drainage: Linear Required \_\_\_\_\_ Ft.

Square Feet in Absorption Field 1320

Inspected by Mike Eaker, Soil Scientist  
(SANITARIAN)

Permit No. 3439 Date 5/13/88

