

FACTORS		PROFILES																		
		1	2	3	4	5	6	7	8	9	10									
LANDSCAPE POSITION	.1940																			
SLOPE (%)	.1940	SS																		
HORIZON 1 DEPTH		0-28	0-24	0-26	0-32															
Texture Group	.1941(A)(1)	LS/SL	LS/SL	LS/SL	LS/SL															
Consistence	.1941																			
Structure	.1941(A)(2)																			
Mineralogy	.1941(A)(3)																			
HORIZON 2 DEPTH		28-42	24-48	26-42	32-42															
Texture Group	.1941(A)(1)	SCL	SCL	SCL	SCL															
Consistence	.1941	Fr	Fv	Fr	Fr															
Structure	.1941(A)(2)	SBK	SBK	SBK	SBK															
Mineralogy	.1941(A)(3)	SEXP	SEXP	SEXP	SEXP															
HORIZON 3 DEPTH																				
Texture Group	.1941(A)(1)																			
Consistence	.1941																			
Structure	.1941(A)(2)																			
Mineralogy	.1941(A)(3)																			
HORIZON 4 DEPTH																				
Texture Group	.1941(A)(1)																			
Consistence	.1941																			
Structure	.1941(A)(2)																			
Mineralogy	.1941(A)(3)																			
SOIL WETNESS	.1942																			
RESTRICTIVE HORIZON	.1944																			
SAPROLITE	.1943/.1956																			
CLASSIFICATION	.1948	PS	PS	PS	PS															
LONG TERM ACCEPTANCE RATE	.1955	.6	.5	.5	.5															



24" ditches
240 dia
(3x80')

