


SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME _____

DATE _____

FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		0-34	0-26	0-19	0-26	0-24								
Texture Group	.1941(A)(1)	SL	SL	SL	SL	SL								
Consistence	.1941	1	1	1	1	1								
Structure	.1941(A)(2)	qr	qr	qr	qr	qr								
Mineralogy	.1941(A)(3)	ncxp	ncxp	ncxp	ncxp	ncxp								
HORIZON 2 DEPTH		34-36	26-36	19-24	26-36	24-36								
Texture Group	.1941(A)(1)	SCL	SCL	SCL	SCL	SCL								
Consistence	.1941	fr	fr	fr	fr	fr								
Structure	.1941(A)(2)	sbk	sbk	sbk	sbk	sbk								
Mineralogy	.1941(A)(3)	sxyp	sxyp	sxyp	sxyp	sxyp								
HORIZON 3 DEPTH				24-36		32-36								
Texture Group	.1941(A)(1)			SCL		SC								
Consistence	.1941			fr		fr								
Structure	.1941(A)(2)			sbk		sbk								
Mineralogy	.1941(A)(3)			sxyp		sxyp								
HORIZON 4 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
SOIL WETNESS	.1942													
RESTRICTIVE HORIZON	.1944													
SAPROLITE	.1943/.1956													
CLASSIFICATION	.1948													
LONG TERM ACCEPTANCE RATE	.1955	.4	.4	.35	.4	.35								



$$\begin{array}{r} 1325 \\ 35 \overline{) 48000} \\ \underline{35} \\ 130 \\ \underline{105} \\ 250 \\ \underline{245} \\ 50 \\ \underline{100} \\ 0 \end{array}$$

$$\begin{array}{r} 458 \\ 3 \overline{) 1373} \\ \underline{12} \\ 17 \\ \underline{15} \\ 23 \end{array}$$