

CERTIFICATE OF COMPLETION / OPERATIONAL PERMIT

Name: (owner) Shaw Construction Co., Inc. New Installation Septic Tank
Property Location: SR# 1120 Repairs Nitrification Line
Subdivision Ramblewood II Lot # 16
Contractor: Gerald Temple Registration # 9
Basement with Plumbing: Garage:
Water Supply: Well Public Community
Distance From Well: _____ ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system: Conventional Other _____
Size of tank: Septic Tank: 1000 gallons Pump Tank: _____ gallons
Subsurface No. of exact length width of depth of
Drainage Field ditches 3 of each ditch 100 ft. ditches 3 ft. ditches 18-24 in.
French Drain: _____ Linear feet

PERMIT NO. 7345

Date: 22 September, 1993
Inspected by: Paul D. White

Environmental Health Specialist

