

APPLICANT NAME \_\_\_\_\_


SITE/SOIL EVALUATION \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFIL												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		0-12	0-12	0-8	0-8	0-18	0-18	0-10	0-14					
Texture Group	.1941(A)(1)	LS	LS	LS	LS	LS	LS	LS	LS					
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 2 DEPTH		12-24	12-24	8-24	8-24	18-42	18-42	18-36	18-36					
Texture Group	.1941(A)(1)	SCL	SCL	SCL	SCL	SCL	SCL	SCL	SCL					
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 3 DEPTH		24-36	24-36	24-36	24-36					3-42	36-42			
Texture Group	.1941(A)(1)	SC	SC	SC	SC					SC	SC			
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 4 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
SOIL WETNESS	.1942									35	42			
RESTRICTIVE HORIZON	.1944			ep24	ep24									
SAPROLITE	.1943/.1956													
CLASSIFICATION	.1948													
LONG TERM ACCEPTANCE RATE	.1955					4-5	4-5							

$$\begin{array}{r} 120 \\ 4 \overline{) 480} \\ \underline{4} \\ 0 \end{array}$$

$$\begin{array}{r} 4 \\ 2 \overline{) 8} \\ \underline{8} \\ 0 \end{array}$$



To be either  
 torn down  
 or used as  
 storage building  
 per ~~owner's~~ owner's

30

50



4

1

3

2