

CERTIFICATE OF COMPLETION / OPERATIONAL PERMIT

Name: (owner) Peterbilt of Dunn New Installation Septic Tank
 Property Location: SR# 1835 Repairs Nitrification Line
 Subdivision _____ Lot # _____
 Contractor: Gerald Temple Registration # 9
 Basement with Plumbing: Garage:
 Water Supply: Well Public Community
 Distance From Well: 50 ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system: Conventional Other _____
 Size of tank: Septic Tank: 217 gallons Pump Tank: _____ gallons
 Subsurface Drainage Field No. of ditches 3 exact length of each ditch 100 ft. width of ditches 3 ft. depth of ditches 18-24 in.
 French Drain: _____ Linear feet

PERMIT NO. 7076

Date: 07-21-93
 Inspected by: J. H. Boyd B.S.
 Environmental Health Specialist

