

# CERTIFICATE OF COMPLETION / OPERATIONAL PERMIT

Name: (owner) Darwin Hill  New Installation  Septic Tank  
Property Location: SR# 401  Repairs  Nitrification Line  
Subdivision \_\_\_\_\_ Lot # \_\_\_\_\_  
Contractor: Odell Johnson Registration # 78  
Basement with Plumbing:  Garage:   
Water Supply:  Well  Public  Community  
Distance From Well: 50+ ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system:  Conventional  Other \_\_\_\_\_  
Size of tank: Septic Tank: 1000 gallons Pump Tank: \_\_\_\_\_ gallons  
Subsurface Drainage Field No. of ditches 3 exact length 100 ft. width of ditches 3 ft. depth of ditches 24 in.  
French Drain: \_\_\_\_\_ Linear feet

PERMIT NO. 8070

Date: 2-1-94

Inspected by: Thomas J. Boyle

Environmental Health Specialist

