

HTE # \_\_\_\_\_

# OPERATIONS PERMIT

Name: (owner) William J. Sparks  New Installation  Septic Tank  Repair

Property Location: SR# J.R. Wilson Ln.  Nitrification Line  Expansion  
Subdivision \_\_\_\_\_ Lot # \_\_\_\_\_ Tax ID # \_\_\_\_\_ Quadrant # \_\_\_\_\_

Contractor: Gerald Temple Registration # \_\_\_\_\_

Basement with Plumbing:  Garage:

Water Supply:  Well  Public  Community  
Distance From Well: 100 ft.

**Following are the specifications for the sewage disposal system on above captioned property.**


Type of system:  Conventional  Other \_\_\_\_\_

Size of tank: Septic Tank: Existing gallons Pump Tank: \_\_\_\_\_ gallons

Subsurface Drainage Field No. of ditches 6 exact length of each ditch 50 ft. width of ditches 3 ft. depth of ditches 24-36 in.

French Drain Required: \_\_\_\_\_ Linear feet Date: 4/27/2008

PERMIT NO. 21745 Inspected by: Dan McLean R.S.



J.R. Wilson Ln