

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-24	0-28	0-40	0-36										
Texture Group	.1941(A)(1)	LS	LS	LS	LS										
Consistence	.1941	1	1												
Structure	.1941(A)(2)	qv	qf												
Mineralogy	.1941(A)(3)	nexp	nexp												
HORIZON 2 DEPTH		34-42	24-36	40-42	36-42										
Texture Group	.1941(A)(1)	SL	SL	SL	SL										
Consistence	.1941	fr	fr												
Structure	.1941(A)(2)	sbk	sbk												
Mineralogy	.1941(A)(3)	xyp	xyp												
HORIZON 3 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 4 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956														
CLASSIFICATION	.1948														
LONG TERM ACCEPTANCE RATE	.1955	.6	.6												

$$\begin{array}{r} 514 \\ \sqrt{2736} \\ \underline{35} \\ 10 \\ \underline{30} \end{array}$$

$$\begin{array}{r} 470 \\ 3.514 \end{array}$$

2x85  
 2411

