

Rosebud

Septic Tank Inspection Certificate

No 1621

Owner Wellms Realty Co Address Spring Lake
(MUST BE FILLED IN) (MAILING ADDRESS)

Contractor Carter Septic Sub Ser. Address Stidman
(MAILING ADDRESS)

Location of Premises Rolling Springs Sub Div #1 Spring Lake
Lot # 39
(SUBDIVISION, STREET OR ROAD NAME OR NUMBER, LOT NO.)

Details of Septic Tank System

Kind of Material for Tank: Concrete Other

Size of Tank: Length _____ Ft. Width _____ Ft. Depth _____ Ft. Capacity 1000 Gallons

Subsurface Drainage Field No. of Ditches 2 Exact Length of each Ditch 84 Width of Ditches 3 Depth of Ditches 28 Inches

Square Feet in Absorption Field 504 Surface Drainage Required 168 Linear Ft.

Approved by Ken Black
(SANITARIAN)

Permit No. _____ Date 3-24-72