

HARNETT COUNTY HEALTH DEPARTMENT

Septic Tank Inspection Certificate

No 1127

Owner Wellons Realty Co. Address Spring Lake

(MUST BE FILLED IN)

(MAILING ADDRESS)

Contractor Carta Septic Tank Service Address Stedman

(MAILING ADDRESS)

Location of Premises Rolling Springs Sub - Division Lot #32

(SUBDIVISION, STREET OR ROAD NAME OR NUMBER, LOT NO.)

Rt. #1 Spring Lake

Details of Septic Tank System

Kind of Material for Tank:

Concrete

Other

Size of Tank: Length _____ Ft. Width _____ Ft. Depth _____ Ft. Capacity 1000 Gallons

Subsurface Drainage Field No. of Ditches 1 Exact Length of each Ditch 100 Width of Ft. Ditches 6'-2 1/2 Depth of Ft. Ditches 28 Inches

Square Feet in Absorption Field 600 Surface Drainage Required 300 Linear Ft.

Approved by Ken Black
(SANITARIAN)

Permit No. _____ Date 9/22/71