

HARNETT COUNTY HEALTH DEPARTMENT

Septic Tank Inspection Certificate

No 1707

Owner Wellms Realty Co. Address ~~100~~ Spring Lake
(MUST BE FILLED IN) (MAILING ADDRESS)

Contractor Carte Septic Tank Svc Address Stedman Nc
(MAILING ADDRESS)

Location of Premises Raleigh Springs Sub-Division, #1 Spring Lake
(SUBDIVISION, STREET OR ROAD NAME OR NUMBER, LOT NO.)

Lot # 53

Details of Septic Tank System

Kind of Material for Tank: Concrete Other _____

Size of Tank: Length _____ Ft. Width _____ Ft. Depth _____ Ft. Capacity 900 Gallons

Subsurface Drainage Field No. of Ditches 2 Exact Length of each Ditch 100 Width of Ditches 3 Depth of Ditches 30 in Inches

Square Feet in Absorption Field 6000 Surface Drainage Required 200 Linear Ft.

Approved by Ken Blad
(SANITARIAN)

Permit No. _____ Date 11-19-71