

HARNETT COUNTY HEALTH DEPARTMENT

Septic Tank Inspection Certificate

No 2059

Owner Wellons Realty Co. Address Spring Lake  
(MUST BE FILLED IN) (MAILING ADDRESS)

Contractor Carter Septic Tank Address Stamora  
(MAILING ADDRESS)

Location of Premises Rolling Springs Sub - Course Lot  
(SUBDIVISION, STREET OR ROAD NAME OR NUMBER, LOT NO.)

# 89 # 1 Spring Lake

Details of Septic Tank System

Kind of Material for Tank:  Concrete  Other a.r. KB

Size of Tank: Length \_\_\_\_\_ Ft. Width \_\_\_\_\_ Ft. Depth \_\_\_\_\_ Ft. Capacity 1000 Gallons

Subsurface Drainage Field No. of Ditches 2 Exact Length of each Ditch 100 Width of Ft. Ditches 3 Depth of Ft. Ditches 28 Inches

Square Feet in Absorption Field 6000 Surface Drainage Required 200 Linear Ft.

Approved by Ken Bluh  
(SANITARIAN)

Permit No. \_\_\_\_\_ Date 1-24-72