

HARNETT COUNTY HEALTH DEPARTMENT

Septic Tank Inspection Certificate

No 3366

Owner Welles Contractor Address Spring Lake  
 (MUST BE FILLED IN) (MAILING ADDRESS)

Contractor Carta Septic Tank Co Address Stamora  
 (MAILING ADDRESS)

Location of Premises Rolling Spring Subdivision Lot #  
15  
 (SUBDIVISION, STREET OR ROAD NAME OR NUMBER, LOT NO.)

Details of Septic Tank System

Kind of Material for Tank:  Concrete  Other

Size of Tank: Length \_\_\_\_\_ Ft. Width \_\_\_\_\_ Ft. Depth \_\_\_\_\_ Ft. Capacity 900 Gallons

Subsurface Drainage Field No. of Ditches 2 Exact Length of each Ditch 100 Ft. Width of Ditches 3 Ft. Depth of Ditches 32" Inches

Square Feet in Absorption Field 600 Surface Drainage Required 200 Linear Ft.

Approved by Ken Blunt  
(SANITARIAN)

Permit No. \_\_\_\_\_ Date 8-2-72