

HARNETT COUNTY HEALTH DEPARTMENT

Septic Tank Inspection Certificate

No 1561

Owner Wellons Realty Co. Address Spring Lake  
(MUST BE FILLED IN) (MAILING ADDRESS)

Contractor Carter Septic Tank Co. Address Stetson  
(MAILING ADDRESS)

Location of Premises Rolling Spring Subdivision #1 Spring Lake  
Lot #17  
(SUBDIVISION, STREET OR ROAD NAME OR NUMBER, LOT NO.)

Details of Septic Tank System

Kind of Material for Tank:  Concrete  Other \_\_\_\_\_

Size of Tank: Length \_\_\_\_\_ Ft. Width \_\_\_\_\_ Ft. Depth \_\_\_\_\_ Ft. Capacity 900 Gallons

Subsurface Drainage Field No. of Ditches 1 Exact Length of each Ditch 100 Width of Ft. Ditches 6" 2 1/2" Depth of Ft. Ditches 30 in Inches

Square Feet in Absorption Field 6000 Surface Drainage Required 200 Linear Ft.

Approved by Ken Black  
(SANITARIAN)

Permit No. \_\_\_\_\_ Date 6-23-72