

HARNETT COUNTY HEALTH DEPARTMENT

Septic Tank Inspection Certificate

No 1497

Owner Wellco Contractor Address Spring Lake
(MUST BE FILLED IN) (MAILING ADDRESS)

Contractor Carter Septic Tank Inc Address Stedman
(MAILING ADDRESS)

Location of Premises Rolling Spring Subdivision #1 S.W. 1/4
Lot # 20
(SUBDIVISION, STREET OR ROAD NAME OR NUMBER, LOT NO.)

Details of Septic Tank System

Kind of Material for Tank: Concrete Other

Size of Tank: Length _____ Ft. Width _____ Ft. Depth _____ Ft. Capacity 900 Gallons

Subsurface Drainage Field No. of Ditches 1 Exact Length of each Ditch 84 Width of Ft. Ditches 6'-2 in Depth of Ft. Ditches 32 in Inches

Square Feet in Absorption Field 504 Surface Drainage Required 168 Linear Ft.

Approved by Ken Black
(SANITARIAN)

Permit No. _____ Date 6-29-72