

HARNETT COUNTY HEALTH DEPARTMENT

Septic Tank Inspection Certificate

No. 1498

Owner Wellco Contractor Address Spring Lake  
(MUST BE FILLED IN) (MAILING ADDRESS)

Contractor Carter Septic Tank Co Address Stedman  
(MAILING ADDRESS)

Location of Premises Rollins Springs Subdiv #1 Spring Lake  
(SUBDIVISION STREET OR ROAD NAME OR NUMBER, LOT NO.)

Lot # 21

Details of Septic Tank System

Kind of Material for Tank:  Concrete  Other

Size of Tank: Length \_\_\_\_\_ Ft. Width \_\_\_\_\_ Ft. Depth \_\_\_\_\_ Ft. Capacity 900 Gallons

Subsurface Drainage Field No. of Ditches 1 Exact Length of each Ditch 84 Ft. Width of Ditches 6'-2 1/2" Depth of Ditches 28 Inches

Square Feet in Absorption Field 504 Surface Drainage Required 108 Linear Ft.

Approved by Ka Black  
(SANITARIAN)

Permit No. \_\_\_\_\_ Date 6-30-72