

# CERTIFICATE OF COMPLETION / OPERATIONAL PERMIT

Name: (owner) Franklin Hamilton  New Installation  Septic Tank  
Property Location: SR# 1131  Repairs  Nitrification Line  
Subdivision \_\_\_\_\_ Lot # \_\_\_\_\_  
Contractor: Gerald Temple Registration # 9  
Basement with Plumbing:  Garage:   
Water Supply:  Well  Public  Community  
Distance From Well: 65 ft.  $\checkmark$

Following are the specifications for the sewage disposal system on above captioned property.

Type of system:  Conventional  Other \_\_\_\_\_  
Size of tank: Septic Tank: 1000 gallons Pump Tank: \_\_\_\_\_ gallons  
Subsurface Drainage Field No. of ditches 3 exact length of each ditch 100 ft. width of ditches 3 ft. depth of ditches 18-20 in.  
French Drain: \_\_\_\_\_ Linear feet

RMIT NO. 6750

Date: 02-15-93  
Inspected by: John H. Boyd B.S.  
Environmental Health Specialist

