

HTE # REPAIR

# OPERATIONS PERMIT

Name: (owner) RONALD DUNCAN  New Installation  Septic Tank  Repair

Property Location: SR# BILL SHAW RD  Nitrification Line  Expansion  
Subdivision \_\_\_\_\_ Lot # \_\_\_\_\_ Tax ID # \_\_\_\_\_ Quadrant # \_\_\_\_\_

Contractor: GERALD TEMPLE Registration # \_\_\_\_\_

Basement with Plumbing:  Garage:

Water Supply:  Well  Public  Community

Distance From Well: 50 ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system:  Conventional  Other \_\_\_\_\_

Size of tank: Septic Tank: EXISTING gallons Pump Tank: \_\_\_\_\_ gallons


Subsurface Drainage Field No. of ditches 3 exact length of each ditch 70 ft. width of ditches 3 ft. depth of ditches 24-36 in.

French Drain Required: \_\_\_\_\_ Linear feet

Date: 7/5/06

PERMIT NO. 22992

Inspected by: [Signature] ES



\*FILTER INSTALLED IN TANK