

HTE # REPAIR

OPERATIONS PERMIT

Name: (owner) ROBERT MANGUM / MARIE STEPHENS New Installation Septic Tank Repair

Property Location: SR# 1514 MAMIE O'NEAL Nitrification Line Expansion
Subdivision _____ Lot # _____ Tax ID # _____ Quadrant # _____

Contractor: OTIS STRICKLAND Registration # _____

Basement with Plumbing: Garage:

Water Supply: Well Public Community
Distance From Well: 50 ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system: Conventional Other POLYSTYRENE AGG. TRENCH

Size of tank: Septic Tank: 1000 gallons Pump Tank: _____ gallons

Subsurface Drainage Field No. of ditches 3 exact length of each ditch 75 ft. width of ditches 3 ft. depth of ditches 24-18 in.

French Drain Required: _____ Linear feet Date: 7/24/06

PERMIT NO. 23152 Inspected by: [Signature] RS

