Department of Environment, Health and Nat Lesources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #: File #: Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Description

Available Space (.1945) System Type(s) Site LTAR

Owner: Address: Proposed Facility: Location of Site: Water Supply: Evaluation Method Type of Wastewate		Property Recorded:  Public Individual Well Spring Other  d: Auger Boring Pit Cut								
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS					
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR	
		0-16	G/N	JANSKA					3	
		16-79	ARIC	F:551	1-4271026				913	
							2			
		4.0	G/52	JESSP 4:55P						
		24-40	BHC	f:559				5	PS.3	
							-	4 Pour		
								THE STATE OF THE S		
			÷							
								81		
									*	
					(4)					
Descrip	otion		itial R	epair System	Other Factors (.1946): Site Classification (.1948):	[N				

Evaluated By Others Present:

COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	п	S-SAND LS-LOAMY SAND SL-SANDY LOAM L-LOAM SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	1.2 - 0.8 0.8 - 0.6 0.6 - 0.3	VFR-VERY FRIABLE FR-FRIABLE FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	NS-NON-STICKY SS-SLIGHTY STICKY S-STICKY VS-VERY STICKY NP-NON-PLASTIC SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

MINERALOGY

**STRUCTURE** SG-SINGLE GRAIN M- MASSIVE CR-CRUMB **GR-GRANULAR** SBK-SUBANGULAR BLOCKY

SLIGHTLY EXPANSIVE

**EXPANSIVE** 

ABK-ANGULAR BLOCKY PL-PLATY

PR-PRISMATIC Show profile locations and other site features (dimensions, references or benchmark, and North)

