


FACTORS		PROFIL													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-20	0-22	0-24	0-32	0-20									
Texture Group	.1941(A)(1)	US/SL	US/SL	US/SL	US/SL	US/SL									
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 2 DEPTH		28-38	22-38	24-36	32-42	20-36									
Texture Group	.1941(A)(1)	SCL/SL	SCL	SCL	SCL	SCL									
Consistence	.1941	Vfr	Fr	Fr	Fr	Fr									
Structure	.1941(A)(2)	SX(SL)	SX(G)	SX	SX	SX									
Mineralogy	.1941(A)(3)	SXP	SXP	SXP	SXP	SXP									
HORIZON 3 DEPTH				26-42											
Texture Group	.1941(A)(1)			SCL(SL)											
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 4 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
SOIL WETNESS	.1942	wet to touch	wet to touch	wet to touch	wet to touch										
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/1958														
CLASSIFICATION	.1948	P5	P5	P5	P5	P5									
LONG TERM ACCEPTANCE RATE	.1955	.5	.5	.5	.5	.5									

This area is flagged out. Does not match map!



- ① wet to touch - bench drain & elevate with
- ② wet to touch
- ③ wet to touch
- ④ wet to touch
- ⑤ wet to touch
- Need to verify prop. lines & corners 20 Jan 99 UPL