Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #: File #: Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Applicant:  Address: Date Evaluated: \( \sigma / 2 \cdot /									
P R O F I L E #	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY		OTHER PROFILE FACTORS				. 4
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
	154%		1	Nor NSNP Fr 55P				ļ	
		18-30	53K/5C1	Frssp				-	Ps.3
						-	<u> </u>	-	
						-		ļ	
						-	-		
			i e						
		34	74						

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948)
Available Space (.1945)			Evaluated By:
System Type(s)		d5 To	Others Present:
Site LTAR		13	Outeb a reservi

## COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET	
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	1	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY	
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	И	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	SS-SLIGHTY STICKY S-STICKY VS-VERY STICKY	
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3	DIPONIAL MELTINA	NP-NON-PLASTIC SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC	

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

MINERALOGY SLIGHTLY EXPANSIVE EXPANSIVE

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB

GR-GRANULAR

SBK-SUBANGULAR BLOCKY

ABK-ANGULAR BLOCKY

PL-PLATY

PR-PRISMATIC Show profile locations and other site features (dimensions, references or benchmark, and North)