Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Available Space (.1945) System Type(s)
Site LTAR

Sheet: Property ID: Lot #: File #: Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Address: Proposed Facility: Location of Site: Water Supply: Evaluation Method Type of Wastewate		Property Recorded:  ☐ Public ☐ Individual ☐ Well ☐ Spring ☐ Other  d: ☐ Auger Boring ☐ Pit ☐ Cut ☐ Cu							
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
	45670	0-20	ofLs	JENSNI					
3		20.30	584150	Fr55P					PS.4
		0-22	G/cs	VENSOR					
		22-42	SBK ( Se	V KNSP					85
		6-19	G-/65	She WSOP					
		19-42	534/C	V Fr SSP					B.4
Descri		S	Initial Repair System System		Other Factors (.1946): Site Classification (.1948): Pl Evaluated By: Others Present: April 1 Helle 2011				
System	le Space (.194 Type(s)	5)		25%					
Site I T	AR			-					

COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET	
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	NS-NON-STICKY	
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6		SS-SLIGHTY STICKY S-STICKY VS-VERY STICKY NP-NON-PLASTIC SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC	
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3			

ΙV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB

MINERALOGY SLIGHTLY EXPANSIVE

**EXPANSIVE** 

GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY PR-PRISMATIC

Show profile locations and other site features (dimensions, references or benchmark, and North)