

# OPERATIONS PERMIT

*Attempt to Repair*

Name: (owner) Harding  New Installation  Septic Tank  
 Property Location: SR# HURON  Repairs  Nitrification Line  
 Subdivision STARWOOD Lot # \_\_\_\_\_  
 TAX ID# \_\_\_\_\_ Quadrant # \_\_\_\_\_  
 Contractor: W. Sharpe Registration # \_\_\_\_\_

Basement with Plumbing:  Garage:

Water Supply:  Well  Public  Community

Distance From Well: 50 min ft.

**Following are the specifications for the sewage disposal system on above captioned property.**

Type of system:  Conventional  Other \_\_\_\_\_

Size of tank: Septic Tank: existing gallons Pump Tank: \_\_\_\_\_ gallons

Subsurface Drainage Field No. of ditches 2 exact length of each ditch 75 ft. width of ditches \_\_\_\_\_ ft. depth of ditches \_\_\_\_\_ in.

French Drain: \_\_\_\_\_ Linear feet

Date: 10/31/96

PERMIT NO. \_\_\_\_\_

Inspected by: J. U. ARS  
Environmental Health Specialist

