OPERATIONS PERMIT

| Name: (owner) (| DAYNE Blockman | New Installation | Sentic Tank |
|------------------------------|--|--|----------------------------|
| | SR#_/80Z | | |
| Troporty Boomion. | Subdivision Across from To | Land St. March | |
| | TAX ID# | 0 | |
| Contractor: Don | S GAHi | | |
| Basement with Plun | and the second s | ige: | |
| Water Supply: | Well Public Com | | |
| Distance From Well | :ft. | | |
| Following are the s | specifications for the sewage disp | posal system on above caption | ned property. |
| _ | 4 | | |
| | Conventional Othe | | |
| Size of tank: | Septic Tank: 1000 gallons | Pump Tank: g | allons |
| Subsurface Drainage Field | No. of exact length of each ditch | width of ft. ditches 3 ft. | depth of ditches 18-28 in. |
| French Drain: | Linear feet | | |
| | Ι | Date: 7-23- | 56 |
| PERMIT NO/ | 0599 | inspected by: Sames C | Markarte |
| | | Environmental | Health Specialist |
| | | | |
| | | Reporte | |
| | | 19 | |
| | 17 | To the state of th | |
| | | | |
| | Home | e | |
| | | 12 | |
| | | DRT YE | |
| | | | |
| | | | |
| | < n 18h | 17 | |