

APPLICANT NAME

DATE

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-16	0-18	0-18	0-14	0-18	0-12								
Texture Group	.1941(A)(1)	SL/LS	LS/LL	LS/SL	LS/LL	LS/SL	LS/SL								
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 2 DEPTH		16-36	16-36	18-36	14-36	18-38	12-36								
Texture Group	.1941(A)(1)	SCL	SCL	SCL	SL	SCL	SCL								
Consistence	.1941	Fi	Fi/Fy	Fi	Fi/SCL	Fi/SCL	Fi/SCL								
Structure	.1941(A)(2)	SPC	SPIC	SE/PL	SE/PI	SE/PL	SE/PI								
Mineralogy	.1941(A)(3)	SEXP	SEXP	SEXP	SEXP	SEXP	SEXP								
HORIZON 3 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 4 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
SOIL WETNESS	.1942	—	32"	32"	34"	34"	33"								
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956														
CLASSIFICATION	.1948	PS	PS	PS	PS	PS	PS								
LONG TERM															
ACCEPTANCE RATE	.1955	.4	.4	.3	.4	.4	.3								

Boring full of water at 28'-30" ① SI
 Need to wait 20 days!
 25 Jan-99
 JM

