


SITE/SOIL EVALUATION FOR ON SITE

APPLICANT NAME _____

DATE _____

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-4	0-14	0-22	0-20	0-12	0-34								
Texture Group	.1941(A)(1)	LS/SL	SCL	LS/SL	USPL		LS/SL								
Consistence	.1941		Fi												
Structure	.1941(A)(2)		ASB/C												
Mineralogy	.1941(A)(3)		SEB/EXD												
HORIZON 2 DEPTH		4-24		22-28	20-28	12-24									
Texture Group	.1941(A)(1)	SCL		SCL	SCL	SCL									
Consistence	.1941	0		Ufr	Ufr	fi									
Structure	.1941(A)(2)			SPL	Stdy										
Mineralogy	.1941(A)(3)	EXD		EX(SB)	EXD	exp									
HORIZON 3 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 4 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
SOIL WETNESS	.1942	10	12"	25"	26"	21									
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956														
CLASSIFICATION	.1948														
LONG TERM ACCEPTANCE RATE	.1955	X	X	?	?										



→ clear 50' back from wood line to the tall timber (poplar trees)



03 Feb 99

① 0-26 CS/IL
abt massive
mineralogy


⑧

② 0-42 CS/IL
out at 36"

⑩

③ 0-42 CS/IL

⑩



met on-site

12" swell & lay dirt
on the low side
of swell
200' feet !!