

OPERATIONS PERMIT *A Hempt To Repair*

Name: (owner) Julia McAllister New Installation Septic Tank
 Property Location: SR# 2330 Ridge Run Repairs Nitrification Line
 Subdivision River Bluff Lot # 14
 TAX ID# _____ Quadrant # _____
 Contractor: Hal Brown Registration # _____

Basement with Plumbing: Garage:

Water Supply: Well Public Community

Distance From Well: 50m ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system: Conventional Other _____

Size of tank: Septic Tank: exist gallons Pump Tank: _____ gallons

Subsurface Drainage Field No. of ditches 3 exact length of each ditch 110 ft. width of ditches 3 ft. depth of ditches 18-24 in.

French Drain: _____ Linear feet

Date: 5-13-98 *Verneth [Signature]*

PERMIT NO. 14092

Inspected by: J. W. [Signature]
Environmental Health Specialist

