Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Description

Site LTAR

Available Space (.1945) System Type(s)

Initial

System

Repair System

Sheet: Property ID: Lot #: File #: Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Address: Proposed Facility: Location of Site: Water Supply: Evaluation Method Type of Wastewate		Property Recorded:  Public Individual Well Spring Other  d: Auger Boring Dit Cut									
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS						
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	Soi Wetn Cole	l ess/	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR	
	1539	0-36	clls	STATE							
		JÇ-48	soulsci	FISSP						PS. 6	
		0.24	0/15	JANSAP TISTIP							
		24-48	SSU/SCI	FISTEP	20 5					18.5	
				-3							
							_				
											_

Other Factors (.1946): Site Classification (.1948):

Evaluated By:

Others Present:

COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	GROUP	<u>TEXTURES</u>	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET	
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY	
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC	
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC	

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY
PR-PRISMATIC

MINERALOGY SLIGHTLY EXPANSIVE

SIC-SILTY CLAY 0.4 - 0.1

EXPANSIVE

C-CLAY SC-SANDY CLAY

IV

