


SITE/SOIL EVALUATION ON-SITE

APPLICANT NAME _____


DATE _____

FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		0-12	0-12	0-36	0-42	0-40	0-42							
Texture Group	.1941(A)(1)	LS/SL	LS/SL	LS/SL	LS/SL	LS/SL	LS/SL							
Consistence	.1941			Fr	Fr									
Structure	.1941(A)(2)			Gr	Gr									
Mineralogy	.1941(A)(3)			NEXP	NEXP									
HORIZON 2 DEPTH		12-36	12-42			12-44								
Texture Group	.1941(A)(1)	SCL	SCL			SCL								
Consistence	.1941	Fv/Fi	Fi			Fi								
Structure	.1941(A)(2)	SBIL	SBIL			SBIL								
Mineralogy	.1941(A)(3)	SEXP	SEXP			SEXP								
HORIZON 3 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 4 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
SOIL WETNESS	.1942													
RESTRICTIVE HORIZON	.1944													
SAPROLITE	.1943/.1956													
CLASSIFICATION	.1948	PS		PS	PS	PS	S							
LONG TERM ACCEPTANCE RATE	.1955	.4		.7	.7	.6	.7							

SL/SE
SL/PL
Soil wet to touch at 24" (out)
beach sand washed at 36"



Layout
3x110 lines
18-22' ditches on contour



SR 2030

(Central Corner) FPKN

N 66° 04' 39" E

89.40'

move house 10 feet toward road

SITE PLAN APPROVAL

DISTRICT N/A USE DWMH

#BEDROOMS 4

Date 8-20-98 Mr Buckland
Zoning Administrator

Fire Hydrant
FRB

Pump to Comp. Repair

rnice Lee Thomas
Book 875, Page 276

N 03° 30' 44" E

222.89'

256.21'



38

207.86'

0.83 Acre - Total
-0.07 Acre - Road R/W
0.76 Acre - Net

metal & wooder stake

FIP

100

S 68° 53' 52" W

Low/Wet Area

218.43'

Prentis L. McLean
Deed Book 561, Page 142

FRB (Contr)