

SITE/SOIL EVALUATION  
FOR  
ON-SITE WASTE WATER

4/22/95

APPLICANT: Donald Dickman PHONE: \_\_\_\_\_ APPLICATION DATE: \_\_\_\_\_  
ADDRESS: \_\_\_\_\_  
COUNTY: Harnett PROPERTY SIZE: \_\_\_\_\_ PROPOSED FACILITY: \_\_\_\_\_  
LOCATION OF SITE: \_\_\_\_\_  
WATER SUPPLY: On-Site Well \_\_\_\_\_ Community \_\_\_\_\_ Public ☒ Other \_\_\_\_\_ EVALUATION BY: Auger Boring ☒ Pit \_\_\_\_\_ Cut \_\_\_\_\_

| FACTORS             |             | PROFILES |       |       |   |   |   |   |   |   |    |
|---------------------|-------------|----------|-------|-------|---|---|---|---|---|---|----|
|                     |             | 1        | 2     | 3     | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
| LANDSCAPE POSITION  | .1940       |          |       |       |   |   |   |   |   |   |    |
| SLOPE (%)           | .1940       |          |       |       |   |   |   |   |   |   |    |
| HORIZON 1 DEPTH     |             | 0-16     | 0-16  | 0-16  |   |   |   |   |   |   |    |
| Texture Group       | .1941(A)(1) | S:L      | S:L   | S:L   |   |   |   |   |   |   |    |
| Consistence         | .1941       |          |       |       |   |   |   |   |   |   |    |
| Structure           | .1941(A)(2) |          |       |       |   |   |   |   |   |   |    |
| Mineralogy          | .1941(A)(3) |          |       |       |   |   |   |   |   |   |    |
| HORIZON 2 DEPTH     |             | 16-38    | 16-38 | 16-38 |   |   |   |   |   |   |    |
| Texture Group       | .1941(A)(1) |          |       |       |   |   |   |   |   |   |    |
| Consistence         | .1941       |          |       |       |   |   |   |   |   |   |    |
| Structure           | .1941(A)(2) |          |       |       |   |   |   |   |   |   |    |
| Mineralogy          | .1941(A)(3) |          |       |       |   |   |   |   |   |   |    |
| HORIZON 3 DEPTH     |             |          |       |       |   |   |   |   |   |   |    |
| Texture Group       | .1941(A)(1) |          |       |       |   |   |   |   |   |   |    |
| Consistence         | .1941       |          |       |       |   |   |   |   |   |   |    |
| Structure           | .1941(A)(2) |          |       |       |   |   |   |   |   |   |    |
| Mineralogy          | .1941(A)(3) |          |       |       |   |   |   |   |   |   |    |
| HORIZON 4 DEPTH     |             |          |       |       |   |   |   |   |   |   |    |
| Texture Group       | .1941(A)(1) |          |       |       |   |   |   |   |   |   |    |
| Consistence         | .1941       |          |       |       |   |   |   |   |   |   |    |
| Structure           | .1941(A)(2) |          |       |       |   |   |   |   |   |   |    |
| Mineralogy          | .1941(A)(3) |          |       |       |   |   |   |   |   |   |    |
| SOIL WETNESS        | .1942       |          |       |       |   |   |   |   |   |   |    |
| RESTRICTIVE HORIZON | .1944       |          |       |       |   |   |   |   |   |   |    |
| APROLITE            | .1943/1956  | 32       | 32    | 32    |   |   |   |   |   |   |    |
| CLASSIFICATION      | .1948       |          |       |       |   |   |   |   |   |   |    |
| LONG TERM           | .1955       | 4        | 4     | 4     |   |   |   |   |   |   |    |
| ACCEPTANCE RATE     |             |          |       |       |   |   |   |   |   |   |    |

AVAILABLE SPACE (.1945): \_\_\_\_\_ SITE LONG TERM  
OTHER FACTORS (.1946): \_\_\_\_\_ ACCEPTANCE RATE: 4  
SITE CLASSIFICATION (.1948): \_\_\_\_\_ SYSTEM TYPE: \_\_\_\_\_  
EVALUATED BY: Aslew OTHERS PRESENT: \_\_\_\_\_  
REMARKS: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

