

SITI OIL EVALUATION FOR ON TE WASTEWATER

APPLICANT NAME _____

DATE _____

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940	L	L	L	L	L	L				
SLOPE (%)	.1940	0-5	0-2	0-2	0-2	0-2					
HORIZON 1 DEPTH		0-12	0-18	0-12	0-18	0-12					
Texture Group	.1941(A)(1)	SL	SL	SL	SL	SL					
Consistence	.1941	FR	PK	PK	PK	PK					
Structure	.1941(A)(2)	GM	GM	GM	GM	GM					
Mineralogy	.1941(A)(3)	1/1	1/1	1/1	1/1	1/1					
HORIZON 2 DEPTH		12-36	18-36	12-36	18-36	12-36					
Texture Group	.1941(A)(1)	SC	SC	SC	SC	SC					
Consistence	.1941	FR	PK	PK	PK	PK					
Structure	.1941(A)(2)	APM	APM	APM	APM	APM					
Mineralogy	.1941(A)(3)	2/1	2/1	2/1	2/1	2/1					
HORIZON 3 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
SOIL WETNESS	.1942	36	36	36	36	36					
RESTRICTIVE HORIZON	.1944	-									
SAPROLITE	.1943/.1956	-									
CLASSIFICATION	.1948	P5	P5	P5	P5	P5					
LONG TERM											
ACCEPTANCE RATE	.1955	.4	.4	.4	.4	.4					

0-14-16-18

SL

FALC 1:1

18-36 SC-C-211 36" +

FALCABLE

Hone

NEEDS

to

Be

SLIDING

UP

10'

make
61'

