# SITE SOIL EVALUATION FOR ON-SITE WASTEWATER

**APPLICANT NAME** _____ **DATE** _____

| FACTORS | | PROFILES | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
| LANDSCAPE POSITION | .1940 | | | | | | | | | | |
| SLOPE (%) | .1940 | | | | | | | | | | |
| HORIZON 1 DEPTH | | 0-18 | 0-20 | 0-38 | 0-42 | 0-48 | | | | | |
| Texture Group | .1941(A)(1) | LS/SL | LS/SL | LS/SL | LS/SL | LS/SL | | | | | |
| Consistence | .1941 | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | |
| HORIZON 2 DEPTH | | 18-36 | 20-32 | | | | | | | | |
| Texture Group | .1941(A)(1) | SCL | SCL | | | | | | | | |
| Consistence | .1941 | FR | | | | | | | | | |
| Structure | .1941(A)(2) | SBK | | | | | | | | | |
| Mineralogy | .1941(A)(3) | SE XO | | | | | | | | | |
| HORIZON 3 DEPTH | | 36-42 | 32-40 | | | | | | | | |
| Texture Group | .1941(A)(1) | LS/SCL | SCL/SL | | | | | | | | |
| Consistence | .1941 | FR | | | | | | | | | |
| Structure | .1941(A)(2) | GR/CBK | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | |
| HORIZON 4 DEPTH | | | | | | | | | | | |
| Texture Group | .1941(A)(1) | | | | | | | | | | |
| Consistence | .1941 | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | |
| SOIL WETNESS | .1942 | — | — | — | — | — | | | | | |
| RESTRICTIVE HORIZON | .1944 | | | | | | | | | | |
| SAPROLITE | .1943/.1956 | | | | | | | | | | |
| CLASSIFICATION | .1948 | PS | PS | PS | S | S | | | | | |
| LONG TERM ACCEPTANCE RATE | .1955 | .5 | .5 | .8 | .8 | .8 | | | | | |