

SOIL/SITE EVALUATION

for

-SITE WASTEWATER SY

EM

OWNER: Rodger Early APPLICANT: _____
 ADDRESS: _____ APPLICATION DATE: 6-12-97 DATE EVALUATED: 2-19-97
 PROPOSED FACILITY: SWMIT PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: 4.48 AC.
 LOCATION OF SITE: SR 1106 PROPERTY RECORDED: _____
 WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other _____
 EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut _____
 TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed _____

P R O F I L E #	.1940 LAND- SCAPE POSITION/ SLOPE %	HORI- ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941)		OTHER PROFILE FACTORS				PROFILE CLASS & LTAR
			.1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	.1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	
1	L 0-17%	0-36	LS	VFR					S e.p
		36-48	SL	VFR					
2	L	0-30	LS	VFR					S e.p
		30-48	SL	VFR					
3	L	0-30	LS	VFR					S e.p
		30-48	SL	VFR					
4		0-30	LS	VFR					S e.p
		30-48	SL	VFR					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM	OTHER FACTORS (.1946):
Available Space (.1945)	OK	OK	SITE CLASSIFICATION (.1948):
System Type(s)	CONV.	CONV.	EVALUATED BY: <u>JH Early</u>
Site LTAR	e.p	e.p	OTHER(S) PRESENT: <u>Overrun</u>