Nº 12806

OPERATIONS PERMIT

Name: (owner)	Carol Fish		New Installation	Septic Tank
Property Location:	SR#/539		Repairs	Nitrification Lin
	Subdivision		Lot #	
	TAX ID#			
Contractor:	Hurold Chappell		Registration #	
Basement with Plum	bing:	Garage:		
Water Supply:	Well Public	Community		
Distance From Well:	50r ft.			
Following are the s	pecifications for the sewag	e disposal syst	em on above captione	d property.
	_	01.	1 1 = 1	e.1 1005-95-3R
Type of system:		,	ene Aggregate Trench 3	
Size of tank:	Septic Tank: 1000 gall	ons Pur	mp Tank: gal	lons
Subsurface Drainage Field	No. of exact lend ditches 2 of each ditches	gth	width of de	epth of
	Linear feet $\leq R$		untenesnt. di	itelies / m.
Fielicii Dialli.	Linear rect 3/0		- 4-199	
PERMIT NO. 16	245	Inspected b	by: Aenus O. F. Environmental H	Sayu R.S.
	DW m/4	SWMH System] Livionine year 1	gaini Speciansi