

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

OWNER: Annie Flynn APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: 8-5 DATE EVALUATED: 9-7-96
PROPOSED FACILITY: Dw MH PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: 1.35 AC
LOCATION OF SITE: SR 1109 PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut _____
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed _____

P R O F I L E #	.1940 LAND- SCAPE POSITION/ SLOPE %	HORI- ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941)		OTHER PROFILE FACTORS				PROFILE CLASS & LTAR
			.1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	.1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	
1	L	0-32	LS	VFR	Cr 2" at 32"				P
		32-48	SL						
2	L	0-40	LS	VFR					
		40-48	SL	FR					
3	L	0-48	LS	VFR					
4		0-35	LS	VFR					
		35-48	SL	VFR					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM	OTHER FACTORS (.1946): SITE CLASSIFICATION (.1948): <u>PS</u> EVALUATED BY: <u>JH Early</u> OTHER(S) PRESENT: _____
Available Space (.1945)	OK	OK	
System Type(s)	CONV.	CONV.	
Site LTAR	.8	.8	

2 of 75