Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #: File #: Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Available Space (.1945)

System Type(s) Site LTAR

Locati Water Evalua		Applicated Aug	Pro	te Evaluated: 8 (2) sign Flow (.1949): operty Recorded: Individual Pit Industrial	Well Cut	perty Size: Spring   Mixed	Other			
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY		OTHER PROFILE FACTORS					
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR	
	05%	0-29	6/5	VENDE						
		29-42	5/2K/SC	1 Fossol	,				15.6	
		0-3	56/6/	JAVIST TASS			-			
	,	78-48	SBRISG	FrosP	'				N.6	
								-		
							-	-		+
								-		-
								-		_
			1.	· 0				-	-	-
		1 .		h.				-		
								-		
			-					-		
-								+	+	_
Description Initial Repair System System			Other Factors (.1946): Site Classification (.1948):							

Evaluated By: Dr Others Present:

COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	1	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	П	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY
PR-PRISMATIC


MINERALOGY SLIGHTLY EXPANSIVE

SIC-SILTY CLAY 0.4 - 0.1

**EXPANSIVE** 

C-CLAY SC-SANDY CLAY

ΓV



Department of Environment, Health and Nat Division of Environmental Health On-Site Wastewater Section

Site LTAR

lesources

Sheet: Property ID: Lot #: File #:

Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Location Water Evalua		Applican	Pro	☐ Pit	Property States		ner				
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941 .1941 Structure/ Consistence Texture Mineralogy			Soil         .1943         .1956         .1944           Wetness/         Soil         Sapro         Restr				Profile Class & LTAR	
		0-48	6/45	JENO NI	P				5. 8		
+											
Descrip	otion		nitial F	Repair System	Other Factors (.19 Site Classification (.1	948): 🖍					
Availab	le Space (.194				Evaluated	d By//~					
Available Space (.1945)  System Type(s)  Evaluated By: Others Present:											

COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	<u>GROUP</u>	<u>TEXTURES</u>	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

SIC-SILTY CLAY 0.4 - 0.1 ΙV C-CLAY

SC-SANDY CLAY

MINERALOGY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY

PL-PLATY

SLIGHTLY EXPANSIVE

EXPANSIVE

PR-PRISMATIC Show profile locations and other site features (dimensions, references or benchmark, and North)