CERTIFICATE OF COMPLETION / OPERATIONAL PERMIT

Name: (owner) Sandy Langdon	New Installation	Septic Tank
Property Location: SR# Tunks Rong	Repairs	Nitrification Line
	Lot #	
TAX ID#	Quadrant #	
Contractor: Kenneth Works	Registration # 36	
Basement with Plumbing: Garage:		
Water Supply: Well Public	Community	
Distance From Well: ft.		
Following are the specifications for the sewa	ge disposal system on above ca	aptioned property.
Type of system: Conventional Other _		-
Size of tank: Septic Tank: 1000 gallons		
Subsurface No. of exact length of each ditches of each ditches	h 80 ft. ditches 3 ft.	depth of ditches 18-24 in.
French Drain: Linear feet		
	Date: 1-25-95	
PERMIT NO. <u>10563</u>	Inspected by:: James &	Marates
	Environmental I	rearth Specialist
Hom	AC.	
Hon	N.E.	
1010	411	
(610	Á	
SysTam		
-9		
.*	8	
D Repair	8 0	
->	on such	
	8	
5 ↑		
		Close I May by