

Benson Design Group
15323 McClure Bridge Rd.
Charlotte, N.C. 28277
Phone # 704-578-8688
Fax # 704-541-4739

January 6, 2020

Wake County Building Inspections Department
Wake County Office Building
336 Fayetteville Street Suite 101 Raleigh, NC 27601

Re: Certification Letter for Final Field Inspection of the installation of (21) New Solar Panels located at 94 Donnibrook Run, Fuquay Varina, NC 27526


To whom it may concern,

This letter is attest to the fact that the installation of the PV system installed at the above mentioned address was inspected by NC licensed contractor, working under my supervision, Mr. Stuart Radcliffe NCGC-21680. The installation was designed by me and installed per plans and specifications, will not have a negative impact on the buildings structural design and is in compliance with the 2018 North Carolina Residential Building Code.

If you have any questions concerning the content of what is written above please do not hesitate to contact me.



Richard W. Benson, PE



January 6, 2020

Solar Installation post engineer check.

Stuart Radcliffe
8775 Hickory Nut Trail
Concord NC 28027
GC# NC 21680

January 3, 2020

Certification letter for load verification and installation inspection.

Property description:

94 Donnibrook Run
Fuquay Varina, NC 27526

This letter is to assure that the installation of the solar panels were installed in a professional manner adhering to the manufacturer's specifications.

The 2x8 roof rafters located 16 on center do not appear compromised during installation of solar panels and appear in good condition.

I certify that I, D. Stuart Radcliffe NC and SC General Contractor did a field inspection on the above-mentioned property on 1/2/2020

Stuart Radcliffe