

Installer: Southern Energy Management

Customer: Ian Frady

Subject: PV System Post Construction Inspection

Date: 11/16/2020

## To whom it may concern:

Model Energy, PLLC performed a site visit on November 15, 2020 at 523 Micahs Way N, Spring Lake, North Carolina 28390 and has reviewed the installation details of the PV system that was installed by Southern Energy Management. The review was limited to the structural elements involved in the construction.

The structural installation of the PV system was inspected, it shall not create a negative impact on the building's structural design, and is in compliance with the North Carolina Residential Building Code. In addition, the PV system was installed in accordance with the structural documents submitted for permitting and was installed using standard and sound construction practices.

Thank you,

Andrew King, PE

