
Dawkins, Andre 232 Old Montague 11745 Installation

Customer Information - Street Address



Customer Information - Permit Card



System Information - Gutter Ladder Guard



Roof/Array Information - Photo: Overall Array




Roof/Array Information - Photo: Overall Array



Roof/Array Information - Photo: Overall Array




Roof/Array Information - Photo: Under Array (wire management)




Roof/Array Information - Photo: Under Array (wire management)



Roof/Array Information - Photo: Under Array (wire management)




Roof/Array Information - Photo: Under Array (wire management)



Roof/Array Information - Photo: Under Array (wire management)



Roof/Array Information - Photo: Junction Box Location



Roof/Array Information - Photo: Junction Box Location



Roof/Array Information - Photo: Junction Box Location



Roof/Array Information - Photo: Junction Box Location





Roof/Array Information - Photo: Conduit Run



Roof/Array Information - Photo: Conduit Run



Roof/Array Information - Photo: Conduit Run



Roof/Array Information - Photo: Conduit Run



Report Created: 01/04/2021



Electrical Information - Photo: Main Service Panel



Electrical Information - Photo: Electrical Component Overview



t Run Electrical Information - Photo: Electrical Component Overview

Report Created: 01/04/2021

Electrical Information - Photo: DC Disconnect

Electrical Information - Photo: Inverter(s)





Electrical Information - Photo: Microinverter layout (sketch)



Page 7 of 9





Electrical Information - Photo: Inverter Data Plate



Electrical Information - Photo: Inverter Data Plate



Electrical Information - Photo: Inverter Data Plate



Electrical Information - Photo: Inverter Data Plate



Electrical Information - Photo: Inverter Data Plate



Electrical Information - Photo: Inverter Data Plate



Electrical Information - Photo: AC Disconnect



Electrical Information - Photo: Production Meter

