

*Benson Design Group*  
15323 McClure Bridge Rd.  
Charlotte, N.C. 28277  
Phone # 704-578-8688  
Fax # 704-541-4739

August 26, 2021

Fayetteville Building Inspection Department  
433 Hay Street  
1st Floor - City Hall  
Fayetteville, NC 28302-1846

**Re: Certification Letter for Final Field Inspection of the installation of 23 solar panels located at 71 Spiral Branch Ct., Linden, NC 28356**


To whom it may concern,

This letter is attest to the fact that the installation of the PV system installed at the above mentioned address was designed by me and installed per approved permit plans and specifications and will not have a negative impact on the buildings structure and is in compliance with the 2018 North Carolina residential building code with the latest amendments.

If you have any questions concerning the content of what is written above please do not hesitate to contact me.



Richard W. Benson, PE



Solar Installation post engineer check.

Stuart Radcliffe  
8775 Hickory Nut Trail  
Concord NC 28027  
GC# NC 21680

January 3, 2020

Certification letter for load verification and installation inspection.

Property description:

5016 Stockton Dr  
Raleigh N.C. 27606

This letter is to assure that the installation of the solar panels were installed in a professional manner adhering to the manufacturer's specifications.

The 2x4@24" roof trusses do not appear compromised during installation of solar panels and appear in good condition.

I certify that I, D. Stuart Radcliffe NC and SC General Contractor did a field inspection on the above-mentioned property on 1/2/2020