

Benson Design Group
15323 McClure Bridge Rd.
Charlotte, N.C. 28277
Phone # 704-578-8688
Fax # 704-541-4739

May 20, 2022

Harnett Co Inspections Dept.
420 McKinney Pkwy
Lillington, NC 27546

Re: Certification Letter for Final Field Inspection of the installation of (32) New Solar panels located at 210 Old Field Loop, Sanford, NC 27332


To whom it may concern,

This letter is attest to the fact that the installation of the PV system installed at the above address has been inspected by someone working under my direct supervision. The PV equipment's structural installation has been designed and inspected. The equipment will not create a negative impact on the building's structural design, including any additional loads imposed (dead, snow, wind) and the installation is in compliance with the 2018 North Carolina Residential Code.

If you have any questions concerning the content of what is written above please do not hesitate to contact me.



Richard W. Benson, PE



May 20, 2022