

Installer: SmartSun Solar

Customer: Georgeann Osornio Perez

Subject: PV System Post Construction Inspection

Date: 6/4/2022

To whom it may concern:

Model Energy, PLLC performed a site visit on June 4, 2022 and has reviewed the installation details of the PV system that was installed by SmartSun Solar at 98 Rolling Springs Drive, Spring Lake, NC. The review was limited to the structural elements involved in the installation.

The structural installation of the PV system was inspected, it shall not create a negative impact on the building's structural design and is in compliance with the 2018 North Carolina Residential Building Code. In addition, the PV system was installed in accordance with the structural documents submitted for permitting and was installed using standard and sound construction practices.

Thank you,

Andrew King, PE

