

Subject: PV System Post Construction Structural Inspection

Date: 1/30/2023

Project: Cogdell, Kenneth "Allen" and Kiersten - PV

Address: 3304 Ashe Avenue, Dunn, NC 28334

To Whom it May Concern:

I, or someone under my responsible charge, has performed a post installation structural inspection at the above listed address. The inspection was limited to the structural elements of the installation only.

The structural installation of the PV system shall not create a negative impact on the building's existing structural elements and is in compliance with the 2018 North Carolina Residential Code. In addition, the PV system was installed in accordance with the structural documents submitted for permitting and was installed using standard and sound construction practices.

Andrew King, PE

