



**Harnett County**  
420 McKinney Pkwy  
LILLINGTON, NC 27546  
Phone:  
Fax:

4/20/2023

**SUBJECT: ERES2303-0002**  
**ELECTRICAL RESIDENTIAL**

To: BARCIA JIMMY

Here are the results of all Inspections located at **234 CHEDWORTH DR:**

Inspection Type: ROUGH IN  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: Justin Ryan McLeod  
Result:  
Remarks:  
Notes:

Inspection Type: FINAL\*\*  
Scheduled Date/Time: 4/11/2023  
Completed Date/Time: 4/11/2023  
Inspector: John B Kokoszka  
Result: DISAPPROVED  
Remarks: eTRAKiT Inspection Request  
Notes: 4/10/2023 11:40 AM Kelsey Lemburg

Contact Name: Kelsey Lemburg  
Site Address: 234 CHEDWORTH DR  
Phone: 9198071361  
e-Mail: office@ready.solar

Wrong size breaker on the inverter. Needs 100 amp



**Harnett County**  
420 McKinney Pkwy

LILLINGTON, NC 27546

Phone:

Fax:

Inspection Type: FINAL\*\*  
Scheduled Date/Time: 4/19/2023  
Completed Date/Time: 4/19/2023  
Inspector: John B Kokoszka  
Result: APPROVED  
Remarks: eTRAKiT Inspection Request  
Notes: 4/18/2023 8:51 AM Kelsey Lemburg

Contact Name: Kelsey Lemburg  
Site Address: 234 CHEDWORTH DR  
Phone: 9198071361  
e-Mail: office@ready.solar