

Installer: SmartSun

Customer: Ricardo Montoya

Subject: PV System Post Construction Inspection

Date: 5/2/2023

## To whom it may concern:

Model Energy, PLLC performed a field inspection on April 26, 2023, to the property located at 31 Roping Ln., Cameron, NC 28326 and has reviewed the installation details of the PV system that was installed by SmartSun. The field inspection was performed by myself, Andrew King (a North Carolina registered design professional), or a person under my direct supervisory control. The review was limited to the structural elements involved in the construction.

The structural installation of the PV system has been inspected, the equipment will not create a negative impact on the building's structural design, including any additional loads imposed (dead, snow, and wind), and is in compliance with the 2018 North Carolina Residential Building Code. In addition, the PV system was installed in accordance with the structural documents submitted for permitting and was installed using standard and sound construction practices.

Thank you,

Andrew King, PE

